

# SAFETY ALERT

## Lifeboat manual winch crank handle



### Description of Process:

The following was found and raised by a vendor during routine maintenance.

### Description of Incident:

During routine maintenance, it was found that the manual winch crank handle of the lifeboat was misaligned due to a bent stowage bracket which prevented full rotation of the handle. This would have prevented the remote launching of the lifeboat by the Coxwain.

- Misaligned manual winch crank handle (3) due to bent stowage bracket preventing full rotation of (2) and remote lifeboat release
- Correctly aligned manual winch crank handle (3) allowing full rotation of the remote lifeboat release (2)



Working together to continuously improve our safety performance

[www.stepchangeinsafety.net](http://www.stepchangeinsafety.net)

# SAFETY ALERT

