


SAFETY ALERT

Teflon pad dropped from crane



Description of Process:

Carrying out lifts utilising the installations forward crane.

Description of Incident:

After completing lifts with the forward crane, the crane operator stowed the crane boom in its cradle. The crane operator observed one of the Teflon pads dislodge and fall from the cradle. The pad initially fell onto the handrail around the tunnel air lock roof before falling further into the main deck forward landing area.

Good practice:

- Ensure planned maintenance is carried out
- Carry out inspections on the crane rest for Potential Dropped Objects

Working together to continuously
improve our safety performance

www.stepchangeinsafety.net